


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-069	Smoke	9/9/2008	ADS/TM	S13YY_010MH	Dry	Yes	1,196.42



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-069	Smoke	9/9/2008	ADS/TM	S13YY_010MH	Dry	Yes	1,196.42

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13YY_010G1	S13YY_010MH	S13AA1013MH	211.6752	8
S13YY_019G1	S13YY_019MH	S13YY_010MH	329.2451	8
S13AA1013G1	S13AA1013MH	S13AA1028MH	280.0945	8
S13AA1012G1	S13AA1012MH	S13AA1028MH	234.1357	8
S13AA1004G1	S13AA1004MH	S13AA1012MH	141.2653	8

Observations & Photos

Obs_ID S1028-069-OB01

Address 3801 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13YY_010MH

Comments Smoke from cleanout in front yard. 3801 Wabash Ave



Picture \S1028-069-OB01-P01.jpg

Comments Front of apartment complex, 3801 Wabash Ave

Obs_ID S1028-069-OB02

Address 3921 Wabash Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13AA1012MH

Comments Smoke from cleanout in front yard. 3921 Wabash Ave



Picture \S1028-069-OB02-P01.jpg

Comments Front of building, 3921 Wabash Ave